

Division: PWP &amp; IWTD, Davanagere

Sub-Division: PWP &amp; IWTD, Harapanahalli

**Form P.W.G.80**  
**REGISTER OF INSPECTION OF PUBLIC BUILDINGS**  
(See paragraph 317 of M.P.W.D. Code)

Sl. No.	Name of Building	Place	Capital Cost of the Building	Maintenance and repair charges incurred	Date of Inspection	By whom inspected	Remarks
1	Taluk Office Building	Harapanahalli	47256	200000		Asst. Exe. Engineer	The Building is in good condition
2	Sub-Registrar Office Building	Harapanahalli	5940	-		--"	--"
3	JMFC Court Bulding	Harapanahalli	4133000	100000		--"	--"
4	Jr. College Building	Harapanahalli	43500	200000		--"	--"
5	Inspection Bungalow	Harapanahalli	7182	200000		--"	--"
6	Inspection Bungalow	Uchangidurga	300000	-		--"	--"
7	Inspection Bungalow	Punabhagatta	300000	-		--"	--"
8	PWD Sub-division Office Building	Harapanahalli	24549	100000		--"	--"
9	Cement Godown	Harapanahalli	10000			--"	--"
10	PWD Section Officers Qtrs	Harapanahalli	40000			--"	--"
11	PWD Asst. Engineers Qtrs.	Harapanahalli	21000			--"	--"
12	PWD Jr. Engineers Qtrs	Harapanahalli	13000			--"	--"
13	PWD Clerks Qtrs.	Harapanahalli	13000			--"	--"
14	Executive Engineers Qtrs	Harapanahalli	200000			--"	--"
15	PWD Section Officers Qtrs	Teligi	9600			--"	Damaged
16	EWS Qtrs	Harapanahalli	95900			--"	The Building is in good condition
17	PWD Supervisors Qtrs.	Arasikere	14210			--"	--"
18	PWD Supervisors Qtrs.	Halawagalu	24000			--"	--"
19	KHB Qtrs. (2 Nos)	Harapanahalli	52200			--"	--"
20	Model Houses	Harapanahalli	5000			--"	--"
21	LIG Buildings (2 to 6 Nos = 5 Nos)	Harapanahalli	160000			--"	--"
22	SRHS Quarters (Twin Unit-1)	Harapanahalli	94300			--"	--"
23	SRHS Quarters (Twin Unit-II)	Harapanahalli	234000			--"	--"
24	EWS Qtrs 3 Nos	Harapanahalli	107730			--"	--"
25	LIG Quarters No.6	Harapanahalli	70000			--"	--"
26	LIG Quarters No.7	Harapanahalli	82500			--"	--"
27	LIG Quarters No.8	Harapanahalli	85400			--"	--"
28	LIG Quarters No.9	Harapanahalli	74500			--"	--"

Assistant Executive Engineer,

Sl. No.	Name of Building	Place	Capital Cost of the Building	Maintenance and repair charges incurred	Date of Inspection	By whom inspected	Remarks
---------	------------------	-------	------------------------------	---	--------------------	-------------------	---------

PWP & IWT Dept., No.6 Sub-Division,  
Harapanahalli.







1	1	PWD Section Officers Qtrs.	H.Halli	PWD Funds	1950	4,000.00	-	PWD	SS in Mud	M'lore Tiles	-	CC with Red Oxide	-	170 Sqm	
	2	Improvements	H.Halli	"	1959-60	9,600.00	-	"							
	3	Improvements	"	"	1961-62										
	4	Reroofing	"	"	1983-84	23,000.00				RCC	-	-	-	-	-
2	1	PWD Asst. Engineer's Qtrs	"	2059	1960-61	21,000.00	-	"	BB Lime	-	-	CC	-	141.00	
	2	Improvements (Roof slab)	"	2059	1997-98	25,000.00									
	3	Repairs & Improvements	"	2216	2005-06	30,000.00									
	4	Repairs & Improvements	"	2216	2006-07	100,000.00									
	5	Repairs & Improvements	"	2216	2007-08	30,000.00									
	6	Repairs & Improvements	"	2216	2008-09q	20,000.00									
3	1	PWD Jr. Engineer's Qtrs.	"		1960-61	13,000.00		PWD	BB Lime	RCC	-	CC	-	90.00	-
	2	Improvements	"		1987-88	8,500.00	-								
	3	Roof Slab Improvements	"	2059	1997-98	25,000.00									
4	1	PWD Clerks Qtrs.	"		1960-61	13,000.00	-	"	"	RCC	-	CC	-	102.00	-
5	1	Executive Engineer Qtrs`	"	283 Housing	1981	200,000.00	-	"							
	2	Compound Wall	"	"	1986	30,000.00	-	-	BB	-	-	-	GF		
	3	KHB Qtrs	"	"	1989-90	15,000.00									
6	1	PWD Supervisors Qtrs	Teligi		1962-63	9,600.00	-	"	BBM	RCC	-	CC	-	75.00	-
	2	Compound Wall	"	PWD	1978-79	10,000.00	-	"	"	-	-	-	-	80.00	-
	3	Improvements	"	"	1989-90	21,000.00									
7	1	EWS Qtrs. No.1 to 5	H.Halli	"	1981-82	95,900.00	45,000	"	Stone Mud Plaster	RCC	TW	CC	GF	151.00	-
	2	Improvements	"	"	1992-93	8,000.00	50,900	"							
8	1	PWD Supervisors Qtrs.	Arasiker e	6/67	14210	-		"	SSM Mud Mortar	RCC	-	CC	-	92.00	-
	2	Impts to Roof	"	1978-79	3200										
9	1	PWD Supervisors Qtrs.	Halawagal u	1976	24400	-		PWD	C.M.	RCC	TW	CC	-	71.60	
10	1	KHB Qtrs. (2 No.s)	H.Halli	1975	52200	-	-	PWD	SSM in CM	RCC	-	CC	-	140.00	

**Assistant Executive Engineer,  
PWP & IWT Dept., No.6 Sub-Division,  
Harapanahalli.**

Remarks (Floor area Sqm)
--------------------------------

--

Total plith area 715.82
-------------------------------

--

--

--

--

--

--

--

--

--

--

--

--

--

-
---

--

--

--

--

--

--

--







-
911.00
77.89
77.89
608.00



19	Halawagalu	"	"	1976	24400		24400	"	"	"	"	"	"	"	"	"	1No
20	Harapanahalli	K.H.B Qtrs (2Nos)	"	1975	52200		52200	"	"	"	"	"	"	"	"	"	2No
21	"	Model Houses-2Nos	"	1972-73	50000		50000	"	"	"	"	"	"	"	"	"	2No
22	"	LIG Bldgs	"					Purchased from KHB	"	"	"	"	"	"	"	"	2No-6No
23	"	SRHS Qtrs Unit I	"	1986	94300		94300	Constructed	"	"	"	"	"	"	"	"	2No
24	"	SRHS Qtrs Unit II	"	1987	213400		213400	"	"	"	"	"	"	"	"	"	2No
25	"	E.W.S Qtrs 3No	"	1986	107730		107730	"	"	"	"	"	"	"	"	"	3No
26	"	LIG Qtrs No 6	"	1986	70000		70000	"	"	"	"	"	"	"	"	"	1No
27	"	LIG Qtrs No 7	"	1987	82500		82500	"	"	"	"	"	"	"	"	"	1No
28	"	LIG Qtrs No 8	"	1987	85400		85400	"	"	"	"	"	"	"	"	"	1No
29	"	LIG Qtrs No 9	"	"	74500		74500	"	"	"	"	"	"	"	"	"	1No
30	Madihalli	Teacher Qtrs 2 no	"	1975	50100		50100	Purchased from KHB	PWD	"	"	"	"	"	"	"	2No

Assistant Executive Engineer,  
PWP & IWT Dept., No.6 Sub-Division,  
Harapanahalli.